


Willows Crossing/Rosewood East






Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Willows Crossing/Rosewood West







GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Parkside Dr SE - North



6/7/2022, 10:51:21 AM







Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community


Web AppBuilder for ArcGIS

Parkside Dr SE - South



6/7/2022, 10:50:15 AM






Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Web AppBuilder for ArcGIS

6th Ave SE/Golf Club PI SE



<all other values>

PSE Street Light

Private Wiring

Disconnect

City of Olym Mingre Roadshid Management, Esri Canada, Esri, HERE, Garmin, Geo Technologies, Inc., USGS, EPA, USDA | Fugro USA Land, Inc. |

EXISTING ELECTRICAL IN TREE WELLS TO BE REMOVED

| | GINAXESE 6TH A | VE SE | | |
|-------|--|--|--|--|
| | SL (J7801) 400 Watts | S LUTADI 400 Watts | | |
| | CITY RESPONSIBILITY: | | | |
| | CUT DOWN TREES IN PRO- PRIOR TO NOTICE TO PRO REPLANT TREES ONCE CC HAS COMPLETED SIDEWAL REPLACEMENT/CONTRACT CONTRACTOR RESPONSIBIL | CEED. NTRACTOR K WORK. | | |
| | REMOVE TREE ROOT BALL EDGE OF CURB; TAKE CAR DAMAGE SURROUNDING A TAKE CARE NOT TO DAMA UTILITIES. HAND DIGGING/ TRUCK MAY BE NECESSAR AREAS. CONTRACTOR TO VERIFY | UP TO E NOT TO REA. GE EXISTING VACUUM RY IN SOME | | |
| | OF UTILITIES. INSTALL ROOT BARRIER P 4-29 AND REPLACE TOPSO GRADE. SIDEWALK REPLACEMENT DIRECTED BY ENGINEER P 4-7 OR 4-9 AS APPLICABLE RESTORE DAMAGED LAND REFER TO BID QUANTITIES ESTIMATED AMOUNT OF W | ER DETAIL VIL TO AS PER DETAIL SCAPING. SFOR | | |
| 1:800 | | | | |


| | | 1:800 | |
|---|----|-------|--------|
| 0 | 35 | 70 | 140 ft |
| 0 | ,, | | 40 m |


Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Sleater Kinney Rd SE at Civic Plaza



6/7/2022, 11:55:26 AM





Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Web AppBuilder for ArcGIS